




Product	Mattress
Item number	R8487378
Colour	Navy blue
Product description	<p>VVS: 777541708 EAN: 5708590360560 HMI: 125838</p>  <p>Mattress for change table, 805 x 1820 mm. Incl. screws. The screws ensure that the mattress is firmly attached to the changing table – both during transfer to and from the changing table and when the changing table is folded away.</p>
Materials	<p>The mattress cover is manufactured from 100% polyester with polyurethane, approved in accordance with Oeko-Tex 100, Class I. It is fire retardant and impermeable to dust mites. The foam filling is flexible polyester-based polyurethane foam, which is also fire retardant and approved in accordance with Oeko-tex 100, Class I. The mattress cover is manufactured from 100% polyester with polyurethane, approved in accordance with Oeko-Tex 100, Class I. It is fire retardant and impermeable to dust mites. The foam filling is flexible polyester-based polyurethane foam, which is also fire retardant and approved in accordance with Oeko-tex 100, Class I.</p>
Ergonomy	<p>The mattress scan be turned over and is made from a pleasant hypoallergenic material with a surface that is easy to wipe down and keep clean.</p>
Features	<p>The mattress is easily removed, which offers flexibility of use and ensures optimum opportunity for effective cleaning over and under the mattress.</p>



Product	Mattress
Item number	R8487378
Cleaning	<p>The product is to be cleaned with hot water or a mild soapy cleaning agent. Do not use chlorine based, corrosive or abrasive cleaners as it may result in the surface being damaged.</p> <p>The following cleaning agents have been tested by Pressalit and may be used, as long as they are diluted according to the instructions on the container.</p> <p>DISINFECTANTS: Sprit (husholdningssprit) Tvættsprit 70% Safe Zone Plus Selgiene Extreme Accel PREvention Wipes Lingettes OxiGenesis from ENVIROX</p> <p>The product must be wiped down with a soft rag wrung out in clear water immediately after cleaning, as some materials may otherwise be discolored and stained, and the surface coating may deteriorate.</p>